

# MP 110 – MP111 – MP112 – MP 115




- > **On/Off/Esc**  
**MP110 MP111 MP112 MP115**
- > Pressure tubes


- > **OK**                      Autozero가

- > Hold/min/max 가 . Hold 가 .
- > On/Off/Esc


- > Hold/min/max 가 .
- > On/Off/Esc




- > Select 가 .
- > UNIT 가 .
- > OK 가 .
- > UNIT 가 .
- > Select 가 . 가 . 가 . : daPa, mmh20, kPa, inWg, mbar , mmHg...
- > OK 가 .
- > UNIT 가 .
- > On/Off/Esc



- > AUTO OFF 가 Select 가 .
- > AUTO OFF OK 가 .
- > Select 가 : 15, 30, 45, 60, 75, 90, 105, 120, OFF
- > AUTO OFF 가 OK
- > On/Off/Esc



- > BEEP 가 Select 가 .
- > OK
- > OFF ON , ON , OFF
- > Select , ON OK
- > BEEP 가
- > On/Off/Esc



- > [Light icon] 가 .
- > [Light icon] 가 .

- > AAA LR03 1.5 V.
- > 가



Once returned to KIMO, required waste collection will be assured in the respect of the environment in accordance to 2002/96/CE guidelines relating to WEEE

**[www.kimo.fr](http://www.kimo.fr)**

**EXPORT DEPARTMENT**  
Boulevard de Beaubourg - Emerainville - BP 48  
77312 MARNE LA VALLEE CEDEX 2  
Tel : + 33.1.60.06.69.25 - Fax : + 33.1.60.06.69.29

